

OSA - 3142-66

14 OCT 1966

SUBJECT: ECP GR-88 Rev. A, Contract CW 6744

Dear Chuck,

This ECP is technically approved by the SPO.
Request you provide [redacted] with formal authority to STATINTL
proceed with it.

STATINTL

[redacted] should provide two Field Service
Bulletins to implement this change - one for antenna
controls and a second for antenna control testers. Also,
[redacted] should change the tester part number after
modification.

STATINTL

We have been advised that [redacted] intends STATINTL
to use a field team to modify antenna control testers which
have been delivered.

Regards,

Ed R

1 Atch
a/s

ccy to:

[redacted]

STATINTL